**Known Issues with WinSLAMM v 9.3.1**                              **9 June 2008**

1. In the biofilter outlet device detailed output file, the program will crash if you select more than three outfall devices and check the Biofilter Stage-Outflow detailed output option.  A work-around for this problem is to add a thin engineered soil layer to the biofilter, with zero removal efficiency and a very high infiltration rate.  This will make the layer transparent to the model output but provide the information the model needs to prevent the program from crashing.  This will be fixed in the next update.