

## **Known Issues with WinSLAMM v 9.4.0**

**18 August 2009**

1. When running the biofilter control practice, an overflow error may occur. This is due to a zero inflow value that causes a divide by zero error. This error only affect the event with the zero inflow, typically a very small portion of the total volume of water routed through the device during a model run. This will be fixed in the next update.
2. When creating an input data file that includes an outfall wet detention pond draining to an outfall biofilter, the file will include duplicate information for the pond and biofilter. This will be fixed in the next update.